### **UP Del Rio Train Derailment**

Brackettville, TX - EPA Region VI POLREP #1 Initial

U.S. ENVIRONMENTAL PROTECTION AGENCY
POLLUTION/SITUATION REPORT
UP Del Rio Train Derailment - Removal Polrep
Initial Removal Polrep



# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region VI

Subject: POLREP #1

Initial

**UP Del Rio Train Derailment** 

A6DP

Brackettville, TX

Latitude: 29.3647475 Longitude: -100.6412888

To: Ragan Broyles, Superfund Division

Lawrence Stanton, EPA HQ

Kelly Crunk, TCEQ

From: Roberto Bernier, FOSC

**Date:** 2/8/2012

Reporting Period: February 7-8, 2012

#### 1. Introduction

# 1.1 Background

Site Number: Contract Number:

D.O. Number: Action Memo Date:

Response Authority: CERCLA Response Type: Emergency

Response Lead: PRP Incident Category: NPL Status: Operable Unit:

Mobilization Date: 2/7/2012 Start Date: 2/7/2012

Demob Date: Completion Date: CERCLIS ID: RCRIS ID:

ERNS No.: NRC 1002329 State Notification: 20120400

FPN#: Reimbursable Account #:

#### 1.1.1 Incident Category

Emergency Response - RP Lead

#### 1.1.2 Site Description:

The site is a Union Pacific Railroad (UPRR and RP) train derailment that occurred at approximately 1005 hours on 7 February 2012 approximately 15 miles east of Del Rio, TX. Thirty-one cars derailed, 19 of which were loaded with materials. Five of the derailed cars are a concern due to potential hazardous materials cargo. Two additional rail cars are also a concern due to oil in addition to its flammable properties.

# 1.1.2.1 Location

Mile post 361, approximately 15 miles east of Del Rio, TX.

# 1.1.2.2 Description of Threat

Three of the derailed cars contained residual amounts of chlorine (toxic/oxidizer), one car contained potassium hydroxide (caustic), and one rail car contained propylene oxide (flammable/oxidizer). The two remaining tank cars of concern contained lubricant oil and nut oil (flammable). No releases from these cars have been reported.

#### 1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

RP lead ER (no removal needed). The following was to determine release or threat of a release:

- Initial entry by Laughlin AFB\* Hazmat team at the request of the local authorities No detection
- RP air monitoring contractor (CTEH) No detection
- EPA START team No detection
- \* Laughlin AFB is located only 5 miles west of incident and was able to support by quickly deploying a Hazmat Team to assess

#### 2. Current Activities

#### 2.1 Operations Section

#### 2.1.1 Narrative

Initial reports from the local authorities indicated a potential release of a chemical due to the derailment. It was supported by the train manifest when quickly submitted by Union Pacific Railroad (UPRR). The manifest included several tank cars carrying chemicals or hazardous material and oil. Due to the line running parallel to HWY 90, the local authorities had to shut down the highway, which is the main connection between Del Rio and San Antonio. Laughlin Air Force Base is located 5 miles to the west of the incident and was able to support the response by deploying a Level A Hazmat team to conduct an initial entry to detect releases of hazardous materials. The team detected no chemical of concern above background levels and UPRR was able to initiate work to stabilize the wreckage and repair the line after coordinating with the local authorities and TCEQ on site. In the meantime EPA OSC Bernier continued coordinating with the locals, TCEQ, and UPRR while en-route with the understanding that no releases or leak were detected, but that the potential still existed.

UPRR started by securing those tank cars carrying hazardous materials and oil. Some had to be up-righted, moved away from the wreck if in the way, and stabilize with sand on the both sides to prevent any structural damage. In the meantime, additional crews concentrated in clearing the rest of the wreckage and debris to allow access to the railroad repair crew. UPRR technical contractor (CTEH) arrived on scene and started with area and spot air monitoring. EPA arrived later with additional meters and coordinated with CTEH. No chemicals of concern were detected above background. Activities involving dealing with those cars with hazardous materials or oil were completed at around 0200 hrs Wednesday morning.

Additional rounds of air monitoring resumed at 0800 hrs and again no chemicals of concern were detected above background. Wreck and debris removal activities were almost complete and demobing with the line repair crew the only ones left on-scene. The railroad was expected to reopen by mid afternoon.

# 2.1.2 Response Actions to Date

EPA OSC Bernier and 5 START contractors mobilized to the site on 7 February 2012 at approximately 1330 hours. EPA also mobilized the Region 6 mobile command post. EPA OSC Bernier and two START contractors arrived onsite at approximately 2230 hours. Two START contractors who mobilized from Houston were already on site. Upon arrival, OSC Bernier and START observed PRP contractors onsite performing response activities. The three derailed cars containing residual chlorine and the car carrying potassium hydroxide had been up-righted and moved to secure locations. The rail cars containing lubricant and nut oils were also upright and secure. The tank car carrying propylene oxide remained in its derailed position. EPA and START monitored PRP contractors upright the propylene oxide tank car. START conducted air monitoring during the process for VOCs, LEL, O2, H2S, and CO. There were not any air monitor readings above background levels. No releases of hazardous materials have been observed by EPA or START. CTEH was performing air monitoring for chlorine, VOCs, LEL, and O2 and it indicated no detections of hazardous concentrations of toxic vapors.

On 8 February 2012, EPA and START returned to the site and all of the damaged rail cars had been removed from the railroad tracks and personnel were continuing to repair the damaged rail line. START conducted air monitoring around the perimeter of the incident, focusing on the areas where the rail cars of concern were located. START monitored for Cl2, VOCs, LEL, O2, H2S, and CO. There were not any detections above background levels.

UPRR personnel and contractors conducted pressure tests on the rail cars of concern and reported that the conditions of the rail cars remained stable. CTEH representatives reported no detections of hazardous concentrations of toxic vapors and that they were preparing to demobilize from the site.

EPA and START demobilized from the site on 8 February 2012.

# 2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

UPRR owns the derailed train.

# 2.2 Planning Section

# 2.2.1 Anticipated Activities

UPRR estimated the rail line would reopen during the afternoon on 8 February 2012. The hazardous material and oil must eventually be removed or transferred from the tank cars. Methods to perform the

transfer are being discussed to start next week. The transfer will depend on safety, structural condition of cars, disposal or product recovery, etc. and could be to either into other tank cars, trucks, or simply lifting the tank by crane and strapped onto rail flat beds for transport.

#### 2.2.1.1 Planned Response Activities

EPA will continue to monitor the progress and will coordinate to resume air monitoring when transfer resumes.

# 2.2.1.2 Next Steps

For the purpose of a final report, air monitoring data sharing between UPRR (CTEH data) and EPA is being coordinated.

#### 2.3 Logistics Section

No information available at this time.

#### 2.4 Finance Section

No information available at this time.

#### 2.5 Other Command Staff

No information available at this time.

# 3. Participating Entities

No information available at this time.

#### 4. Personnel On Site

No information available at this time.

# 5. Definition of Terms

No information available at this time.

# 6. Additional sources of information

No information available at this time.

## 7. Situational Reference Materials

No information available at this time.